
## **CORNER RECORD**

CR-24-405 Agency Index **Document Number** . California SAN JOAQUIN County of City of Brief Legal Description FOUND MONUMENTS EAST OF HARLAN ROAD, PER RS 40-35 S.J.C.R. COORDINATES (Optional) **CORNER TYPE** Elevation ☐ Government Corner ☐ Control X U.S. Survey Foot ☐ Metric Units X Property Meander SEC Horizontal Datum Other Rancho **Epoch Date** Zone Vertical Datum Date of Survey August 3, 2023 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 C.M. WEBER GRANT Other: 8773 X 8771 8765(d) PLS Act Ref .: X Pre-Construction Rebuilt Established Left as found Post-Construction Corner/ X Referenced Reestablished Monument: Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE LOCATION OF THE CORNER(S) ON RS 40-35, SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY AND VALIDITY OF THE MONUMENT(S) FOUND AS ACTUALLY MARKING THE PROPERTY CORNER. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8489 October 15, 2023 the Professional Land Surveyors' Act on 8489 P.L.S. or R.C.E. No. Signed E OF CALIF COUNTY SURVEYOR'S STATEMENT This Corner Record was received and examined and filed **ICENSE** Signed Title County Surveyor's Comment

Page 1 of 2

BPELSG-2016



## REFERENCE

(A)