CR-24-495 CORNER RECORD Agency Index Document Number California San Joaquin City of Stockton County of ___ Brief Legal Description _____ Lots 22, 23, 27, 28, and 29, M.&P. 23-10 **CORNER TYPE COORDINATES (Optional)** E. Government Corner Control Elevation U.S. Survey Foot Meander X Property Units Metric Rancho Horizontal Datum Epoch Date Zone Date of Survey July 9, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 **X** 8771 Other: 8765(d) 8773 PLS Act Ref.: Left as found Rebuilt Pre-Construction Established Corner/ Monument: Post-Construction Found and tagged Reestablished X Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on July 9, 2024 PLS 7889 P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received <u>December 13, 2024</u>

and examined and filed <u>December 19, 2024</u>.

Signed <u>Sames & Haut</u> P.L.S.-or R.C.E. No. 8657

Title <u>County Surveyor</u>



BPELSG-2016 Page 1 of 2

County Surveyor's Comment

LEGEND:

A-C-B

A-D-B

A-E-B

082°24'09"

051°25'43"


046°06'52"

M.&P. MAPS AND PLATS, BOOK AND PAGE, SAN JOAQUIN COUNTY RECORDS

- FOUND CHISELED CROSS
- FOUND 3/4" IRON ROD IN MONUMENT WELL

DESCRIPTION:

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.



42.51'

167.34'

186.40'

133.64'

71.95'

118.41'