
CORNER RECORD

Document Number SAN JOAQUIN California City of STOCKTON County of Brief Legal Description FOUND MONUMENT AT CORNER OF ROSE MARIE LANE AND GEORGETOWN PLACE. **COORDINATES (Optional) CORNER TYPE** N. Elevation Government Corner Control X U.S. Survey Foot Meander **Property** Units Metric Other Rancho Horizontal Datum Epoch Date Zone Date of Survey August 3, 2023 Vertical Datum Complies with Public Resources Code §§8801-8819 C.M. WEBER GRANT Complies with Public Resources Code §§8890-8902 X 8771 8773 Other: 8765(d) PLS Act Ref.: X Pre-Construction Established Rebuilt Left as found Corner/ Monument: Post-Construction Referenced Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE RECORD LOCATION OF THE CORNER(S) ON PM 2-39, SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY AND VALIDITY OF THE MONUMENT FOUND AS ACTUALLY MARKING THE PROPERTY CORNER. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8489 the Professional Land Surveyors' Act on October 15, 2023 8489 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed Signed Title

Agency Index

County Surveyor's Comment



ROSE MARIE LANE

LEGEND		SURVEYOR NOTES
•	FOUND MONUMENT AS NOTED	THIS CORNER RECORD IS BEING FILED TO
•	SET CONTROL POINT	FULFILL THE PRE-CONSTRUCTION
4545	REFERENCE STREET ADDRESS	MONUMENT PRESERVATION REQUIREMENTS
PM	PARCEL MAPS, SAN JOAQUIN COUNTY RECORDS	OF SECTION 8771 OF THE CALIFORNIA
APN	TAX ASSESSOR PARCEL NUMBER	BUSINESS AND PROFESSIONS CODE. IT IS
	TIE LINE	NOT THE RESULT OF A FULLY RESOLVED
	LOT LINE	BOUNDARY SURVEY FOR ANY PARCEL OF
	RIGHT-OF-WAY CENTERLINE	REAL PROPERTY.

REFERENCES

(A) PARCEL MAP BOOK 2, AT PAGE 39, SAN JOAQUIN COUNTY RECORDS