CORNER RECORD

Agency Index **Document Number** California County of SAN JOAQUIN Brief Legal Description RE-ALIGNED THORNTON ROAD NORTH OF STATE HIGHWAY 12 **COORDINATES (Optional) CORNER TYPE** N. Elevation Government Corner Control U.S. Survey Foot Metric Units ☐ Property Meander Horizontal Datum ____ ○ Other Rancho Epoch Date Vertical Datum T.3N, R.5E Date of Survey 5-23-2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: **⊠** 8771 8773 PLS Act Ref: 8765 (d) Rebuilt Pre-Construction Left as found Established Corner/ Monument: Post-Construction Referenced ☐ Found and tagged ☐ Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description (s): FOUND TWO (2) 3/4" REBAR, NOT TAGGED, IN MONUMENT WELLS [3/4" REBAR TAGGED "LS 5250" PER (R1)]; SET EIGHT (8) CONCRETE NAILS WITH BRASS TAG "LS 6953" AS WITNESS CORNERS, ALL AS SHOWN ON SHEET 2.

SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on JUNE 28, 2024
Signed P.L.S. or R.C.E. No6953
COUNTY SURVEYOR'S STATEMENT
This Corner Record was received August 13, 2024
and examined and filed September 6, 2024
Signed Dames & Hart P.L.S. or R.C.E. No. 8657

County Surveyor's Comment _____





