## CORNER RECORD

Government Corner

☐ Found and tagged ☐ Reestablished

X 8771

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ Established

Meander

Rancho

City of N/A

T.3N, R.5E

Corner/

Monument:

**Brief Legal Description** 

PLS Act Ref: 8765(d)

□ Left as found


CR-24-307 Agency Index **Document Number** County of SAN JOAQUIN RE-ALIGNED THORNTON ROAD NORTH OF STATE HIGHWAY 12 **COORDINATES (Optional) CORNER TYPE** Elevation Control Units Metric U.S. Survey Foot ☐ Property Horizontal Datum \_\_\_ ☑ Other Epoch Date Zone Vertical Datum Date of Survey 5-23-2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8773 Other: Pre-Construction Rebuilt Post-Construction Referenced

See sheet #2 for description (s): FOUND ONE (1) 3/4" IRON PIPE TAGGED "LS 6953" IN MONUMENT WELL (R1); SET FIVE (5) CONCRETE NAILS WITH BRASS TAG "LS 6953" AS WITNESS CORNERS, ALL AS SHOWN ON SHEET 2.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with	
the Professional Land Surveyors' Act onJUI	NE 28, 2024
Signed Malynum	_ P.L.S. or R.C.E. No. 6953
COUNTY SURVEYOR'S STATEMENT	
This Corner Record was received August	+ 13, 2024
and examined and filed September 6	, 2024
Signed Sams & Hart	_ P.L.S. <del>or R.C.E</del> . No. <u>8657</u>
Title County Surveyor	<b>-</b> .
County Surveyor's Comment	





Page 2 of 2