
CORNER RECORD

Document Number SAN JOAQUIN , California County of City of Brief Legal Description FOUND MONUMENTS PER CORNER RECORD 23-084, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS AND 6-RS-45. SAN JOAQUIN COUNTY RECORDS. **COORDINATES (Optional) CORNER TYPE** Elevation Government Corner Control X U.S. Survey Foot X Property Units Metric Meander SEC 76 ---Other Rancho Horizontal Datum **Epoch Date** Zone February 14, 2024 Date of Survey Vertical Datum Complies with Public Resources Code §§8801-8819 C.M. WEBER GRANT Complies with Public Resources Code §§8890-8902 X 8771 8773 Other: 8765(d) PLS Act Ref.: Pre-Construction Rebuilt X Left as found Established Corner/ Monument: X Post-Construction Referenced Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8489 April 1, 2024 the Professional Land Surveyors' Act on 8489 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT September 5, 2024 This Corner Record was received September 20, 2024. E. Hart P.L.S. OFR.G.E. No. 8657 and examined and filed LICENSE Signed NO. 8657 Title **County Surveyor's Comment**

CR-24-335

Agency Index



REFERENCES

- (A) CORNER RECORD 23-084, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS
- (B) BOOK OF SURVEYS, VOLUME 6 AT PAGE 45, SAN JOAQUIN COUNTY RECORDS