
CORNER RECORD

Document Number SAN JOAQUIN California City of County of Brief Legal Description FOUND MONUMENTS AS SHOWN ON RECORD OF SURVEY 39-147, SAN JOAQUIN COUNTY RECORDS **CORNER TYPE COORDINATES (Optional)** Elevation Government Corner Control X U.S. Survey Foot Property Units Meander Metric SEC 18 -Other Rancho Horizontal Datum **Epoch Date** Zone July 26, 2022 Date of Survey Vertical Datum Complies with Public Resources Code §§8801-8819 T2S/R9E Complies with Public Resources Code §§8890-8902 8765(d) X 8771 8773 PLS Act Ref.: Other: Left as found Pre-Construction Established Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE RECORD LOCATION OF THE CORNER(S) ON RS 39-147. SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY OR VALIDITY OF THE MONUMENT(S) FOUND AS ACTUALLY MARKING THE PROPERTY CORNER. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8489 May 31, 2023 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. Signed OF CALL COUNTY SURVEYOR'S STATEMENT October 2, 2024 This Corner Record was received and examined and filed LICENSE Signed Title County Surveyor's Comment

CR-24-363

Agency Index

BPELSG-2016 Page 1 of 2



REFERENCE

(A)