
CORNER RECORD

CR-24-364 Agency Index **Document Number** SAN JOAQUIN , California County of City of Brief Legal Description FOUND MONUMENT AS SHOWN ON RECORD OF SURVEY 11-61, SAN JOAQUIN COUNTY RECORDS. ONE MONUMENT NOT OF RECORD. COORDINATES (Optional) **CORNER TYPE** Elevation Government Corner Control X U.S. Survey Foot Units Metric Property Meander SEC 18 ---Other Rancho Horizontal Datum **Epoch Date** July 26, 2022 Date of Survey Vertical Datum Complies with Public Resources Code §§8801-8819 T2S/R9E Complies with Public Resources Code §§8890-8902 X 8771 8773 Other: PLS Act Ref.: 8765(d) X Pre-Construction Rebuilt Established Left as found Corner/ Monument: Reestablished Referenced Post-Construction Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE RECORD LOCATION OF THE CORNER(S) ON RS 11-61, SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY OR VALIDITY OF THE MONUMENT(S) FOUND AS ACTUALLY MARKING THE PROPERTY CORNER. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8489 May 31, 2023 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. Signed OF CALL COUNTY SURVEYOR'S STATEMENT This Corner Record was received and examined and filed LICENSE Signed No. 8657 Title

County Surveyor's Comment



REFERENCE

(A) BOOK If OF SURVEYS, AT PAGE 61 SAN JOAQUIN COUNTY RECORDS