CORNER RECORD Agency Index **Document Number** SAN JOAQUIN California City of County of Brief Legal Description FOUND MONUMENTS EAST OF HARLAN ROAD, PER RS 34-111 AND RS 7-286 S.J.C.R. COORDINATES (Optional) **CORNER TYPE** N. ☐ Government Corner ☐ Control Elevation X U.S. Survey Foot Meander Property Units Metric SEC Rancho Other Horizontal Datum Epoch Date Zone Date of Survey August 3, 2023 Vertical Datum Complies with Public Resources Code §§8801-8819 C.M. WEBER GRANT Complies with Public Resources Code §§8890-8902 X 8771 Other: 8765(d) 8773 PLS Act Ref.: Left as found Established Rebuilt X Pre-Construction Corner/ Monument: Referenced Post-Construction Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE LOCATION OF THE

CORNER(S) ON RS 34-111 AND RS 7-286, SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY AND VALIDITY OF

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

THE MONUMENT(S) FOUND AS ACTUALLY MARKING THE PROPERTY CORNER.

the Professional Land Surveyors' Act on October 15, 2023

Signed 34 5C

P.L.S. or R.C.E. No.

8489



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received

October 25, 2024

and examined and filed

November 5, 2024

Signed

7. Hant P.L.S. OF R.C.E.


Title

ounty Surveyor

County Surveyor's Comment

LICENSE No. 8657

BPELSG-2016 Page 1 of 2



REFERENCES

- (A) RECORD OF SURVEY BOOK 34, AT PAGE 111, SAN JOAQUIN COUNTY RECORDS
- (B) RECORD OF SURVEY BOOK 7, AT PAGE 286, SAN JOAQUIN COUNTY RECORDS