CORNER RECORD

Agency Index Document Number City of _____ STOCKTON ____ County of ___ SAN JOAQUIN Brief Legal Description WEST LINE OF PARCEL "A" PER P.M. 1-82 **CORNER TYPE** COORDINATES (Optional) Government Corner Control Elevation Meander Property U.S. Survey Foot Units Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey October 8, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8765(d) PLS Act Ref.: 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THIS DOCUMENT IS FOR THE PURPOSE OF RESETTING ANY MISSING OR OBLITERATED CORNERS FROM THE WEST LINE OF PARCEL "A", AS SHOWN IN BOOK 1 OF PARCEL MAPS. PAGE 82, SAN JOAQUIN COUNTY RECORDS. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with P. 12-31-24 the Professional Land Surveyors' Act on November 4, 2024 P.L.S. or R.C.E. No. L.S. 7600 Signed 6 COUNTY SURVEYOR'S STATEMENT November 6, 2024 ovember 25, 2024. This Corner Record was received and examined and filed Signed

RPFI SG-2016

County Surveyor's Comment

Title



WONG ENGINEERS, INC.

4578 FEATHER RIVER DRIVE, SUITE A STOCKTON, CA 95219 (209) 476-0011 NOVEMBER 4, 2024 PAGE 2 OF 2

REFERENCES:

(A) P.M. 1-82, SJCR

(B) P.M. 14-114, SJCR 80'

1" = 80'

LEGEND:

(M) **MEASURED**

M&P MAPS & PLATS, BOOK-PAGE P.M. PARCEL MAPS, BOOK-PAGE


SFN SEARCHED, FOUND NOTHING SJCR SAN JOAQUIN COUNTY RECORDS

FOUND MONUMENT AS NOTED

SET MAG NAIL WITH STEEL 0 WASHER STAMPED L.S. 7600

NTERSTATE HIGHWAY ROUTE NO.5

COUNTRY CLUB BOULEVARD



DESCRIPTION:

THIS DOCUMENT IS FOR THE PURPOSE OF RESETTING ANY MISSING OR OBLITERATED CORNERS OF WEST LINE OF PARCEL "A", AS SHOWN IN BOOK 1 OF PARCEL MAPS, PAGE 82, SAN JOAQUIN COUNTY RECORDS.