Agency Index <u>CR-25-DID</u> CORNER RECORD Document Number \_\_\_\_\_\_, Ca City of Stockton County of \_\_\_\_\_ , California Brief Legal Description Lots 287, 288, 289, 290, M.&P. 22-3 **CORNER TYPE COORDINATES (Optional)** N. \_\_\_\_E. Government Corner Control Elevation Meander Property U.S. Survey Foot Units Metric Rancho Other Horizontal Datum Epoch Date Zone Date of Survey December 13, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on December 13, 2024 PLS 7889 Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** January 8, 2025 January 16, 2025 This Corner Record was received and examined and filed

P.L.S. OFR.C.E. No. 8657

**County Surveyor's Comment** 

Signed

Title

LICENSE

No. 8657

## LEGEND:

- M.&P. MAPS AND PLATS, BOOK AND PAGE, SAN JOAQUIN COUNTY RECORDS
  - FOUND CHISELED CROSS PER CORNER RECORD 24-359, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS
  - FOUND 3/4" IRON ROD TAGGED
    "R.C.E. 15831" IN MONUMENT WELL

## **DESCRIPTION:**

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.

