CORNER RECORD

Document Number , California SAN JOAQUIN County of City of STOCKTON Brief Legal Description FOUND CHISELED CROSS IN SIDEWALK NEAR THE SOUTHEAST CORNER OF LOT 67 AS SHOWN IN 24-MP-82, S.J.C.R. **COORDINATES (Optional) CORNER TYPE** E. Government Corner Control Elevation X U.S. Survey Foot Metric X Property Units Meander SEC 28 Other Rancho Horizontal Datum Epoch Date Zone May 16, 2023 Vertical Datum Date of Survey Complies with Public Resources Code §§8801-8819 C.M. WEBER GRANT Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 PLS Act Ref.: 8765(d) Pre-Construction Rebuilt Established Left as found Corner/ X Post-Construction X Referenced Monument: Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s):

SURVEYOR	"S S"	TATE	MENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on

November 12, 2023

Signed

P.L.S. or R.C.E. No.

8489

Agency Index CR-24-227

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received

June 10, 2024

and examined and filed

Signed

June 21, 2024.


Hat P.L.S. OF R.C.E. No. 8657

Title

County Surveyor's Comment

No. 8489

OF CALIF



(A) CORNER RECORD 23-083, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS.