
## CORNER RECORD

**Document Number** County of SAN JOAQUIN Brief Legal Description FOUND MONUMENTS ALONG THE RIGHT-OF-WAY LINES OF JACK TONE BYPASS ROAD. **COORDINATES (Optional) CORNER TYPE** E. Government Corner Control Elevation X U.S. Survey Foot X Property Units Metric Meander SEC Other Rancho Horizontal Datum 36 **Epoch Date** Zone May 4, 2023 Vertical Datum Date of Survey Complies with Public Resources Code §§8801-8819 T4N/R7E Complies with Public Resources Code §§8890-8902 X 8771 Other: PLS Act Ref.: 8765(d) 8773 X Pre-Construction Established Rebuilt Left as found Corner/ Post-Construction Monument: Referenced Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE RECORD LOCATION OF THE CORNER(S) ON RS 26-61, SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY OR VALIDITY OF THE MONUMENT FOUND AS ACTUALLY MARKING THE PROPERTY CORNER. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8489 October 27, 2023 the Professional Land Surveyors' Act on 8489 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT June 10, 2024 This Corner Record was received Mact P.L.S. of R.G.E. No. 8657 and examined and filed Signed Title County Surveyor's Comment

CR-24-232

Agency Index



## REFERENCE

(A) RECORD OF SURVEY BOOK 26 AT PAGE 61. SAN JOAQUIN COUNTY RECORDS

Page 2 of 2 #043-403