CR-24-261 Agency Index: CORNER RECORD Document Number: County of _____SAN JOAQUIN **MANTECA** City of Brief Legal Description MONUMENT AT THE INTERSECTION OF LOUISE AVENUE AND MT DEW AVENUE. COORDINATES (Optional) CORNER TYPE __ E. _____ Government Corner Control Elevation Property Meander U.S. Survey Foot ___ Metric Units - 28 - ○ Other Rancho Horizontal Datum Zone _____ Epoch Date ____ 06-10-2024 Date of Survey Vertical Datum T.1S, R.7E Complies with Public Resources Code SS8801-8819 Complies with Public Resources Code SS8890-8902 8765(d) 8771 8773 Other: PLS Act Ref: ▼ Pre-Construction Left as found **Established** Rebuilt Corner/ Referenced ☐ Post-Construction Monument: Found and Tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND ONE (1) 2.5" BRASS DISK, STAMPED "RCE 18420", IN A MONUMENT WELL AT THE INTERSECTION OF LOUISE AVENUE AND MT DEW AVENUE (NO REFERENCE FOUND). SET FOUR (4) CONCRETE NAILS WITH BRASS TAGS, MARKED "L.S. 6953", AS WITNESS CORNERS. ALL AS SHOWN ON PAGE 2.

SURVEYOR'S STATEMENT

This	Corne	Record	was	prepared	by	me	or	under	my	direction	ın	conformance	with
the	Land S	Surveyors'	Act	on		JUN	E '	17		·	20)24,	

Signed P.L.S. or R.C.E. Number 6953



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 26, 2024

and examined and filed July 12, 2024

Signed P.L.S. or R.C.E. No: 8657

LICENSE No. 8657

County	Surveyor's	Comment	•	 		
		·				

