
## **CORNER RECORD**

Agency Index **Document Number** , California County of SAN JOAQUIN **STOCKTON** City of Brief Legal Description FOUND CHISELED CROSS BETWEEN LOTS 12 AND 13, PER MP 29-8, SAN JOAQUIN COUNTY RECORDS. **COORDINATES (Optional) CORNER TYPE** Elevation Government Corner Control X U.S. Survey Foot Property Metric Units SEC Meander Other Rancho Horizontal Datum Epoch Date Zone Date of Survey April 6, 2023 Vertical Datum Complies with Public Resources Code §§8801-8819 CM WEBER GRANT Complies with Public Resources Code §§8890-8902 8773 Other: 8765(d) X 8771 PLS Act Ref.: X Pre-Construction Rebuilt Established Left as found Corner/ Monument: Referenced Post-Construction Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): THE FOUND MONUMENT(S) SHOWN ON THIS CORNER RECORD WERE FOUND IN THE APPROXIMATE RECORD LOCATION OF THE CORNER(S) ON MP 29-8, SAN JOAQUIN COUNTY RECORDS. I DID NOT VERIFY THE IDENTITY OR VALIDITY OF THE MONUMENTS FOUND AS ACTUALLY MARKING THE PROPERTY CORNER. **SURVEYOR'S STATEMENT** This Corner Record was prepared by me or under my direction in conformance with No. 8489 January 29, 2024 the Professional Land Surveyors' Act on 8489 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT** July 16, 2024 This Corner Record was received and examined and filed Signed Title

**County Surveyor's Comment** 



## **REFERENCES**

(A) MAPS AND PLATS, VOLUME 29, PAGE 8, SAN JOAQUIN COUNTY RECORDS