CR-24-344 CORNER RECORD Agency Index Document Number _____ California City of County of SAN JOAQUIN Brief Legal Description FOUND RAILROAD SPIKE WITH PUNCH, SET FLUSH WITH SURFACE OF ROAD, PER RECORD OF SURVEY 38 RS 138, SAN JOAQUIN COUNTY RECORDS **COORDINATES (Optional) CORNER TYPE** Government Corner | Control Elevation U.S. Survey Foot Property. Units Metric Meander Other Rancho Horizontal Datum Zone _____ Epoch Date _____ Date of Survey AUGUST 23, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8771 Other: PLS Act Ref.: 8765(d) Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND RAILROAD SPIKE WITH PUNCH, SET FLUSH WITH SURFACE OF ROAD, PER RECORD OF SURVEY 38 RS 138, SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with SEPTEMBER 12, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed LICENSE NO. 8657 Signed SĂN JOAQUIN COUNTY SURVEYOR Title

County Surveyor's Comment

BPELSG-2016 Page 1 of 2

