## CORNER RECORD Agency Index Document Number City of County of SAN JOAQUIN Brief Legal Description FOUND 3/4" REBAR WITH PLUG "LS 4124", IN DIRT, IN THE CENTER OF FUHRMAN ROAD, 1994'± NORTHERLY OF EAST COLLIER ROAD PER (41 RS 20), SAN JOAQUIN COUNTY RECORDS **COORDINATES (Optional) CORNER TYPE** N. Government Corner Control Elevation U.S. Survey Foot Meander X Property Units Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey MAY 8, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8765(d) X 8771 Other: PLS Act Ref.: Established Pre-Construction Left as found Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" REBAR WITH PLASTIC PLUG "LS 4124", IN DIRT, IN THE CENTER OF FUHRMAN ROAD, 1994'± NORTHERLY OF EAST COLLIER ROAD, PER (41 RS 20) SAN JOAQUIN COUNTY RECORDS. THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surgeyors' Act on SEPTEMBER 16, 2024 P.L.S. or R.C.E. No. 9667 Signed

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received September 20, 2024


and examined and filed September 26, 2024

Signed P.L.S. or R.C.E. No. 8657

Title SAN JOAQUIN COUNTY SURVEYOR

County Surveyor's Comment

LICENSE No. 8657



BPELSG-2016