CR-24-362 CORNER RECORD Agency Index Document Number _____ San Joaquin Stockton County of California City of Lots 9, 10, 11, M.&P. 19-33 Brief Legal Description **CORNER TYPE** COORDINATES (Optional) N. Elevation Government Corner Control X Property U.S. Survey Foot Metric Meander Units Other Rancho Horizontal Datum Zone Epoch Date Date of Survey August 21, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 X 8771 PLS Act Ref.: 8765(d) 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on August 21, 2024

P.L.S. or R.C.E. No.

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October |

and examined and filed October 15, 2024

Signed James 2 Hart P.L.S. or R.G.E. No. 8657

Title County Surveyor

County Surveyor's Comment

Signed




PLS 7889

M.&P. MAPS AND PLATS, BOOK AND PAGE, SAN JOAQUIN COUNTY RECORDS

- FOUND 3/4" IRON ROD, NO TAG
- FOUND 3/4" IRON PIPE IN ◉ MONUMENT WELL, NO TAG

DESCRIPTION:

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.



A-D-B

052°46'43"

92.26

280.14