Agency Index CR-24-380 CORNER RECORD Document Number City of _____ County of ____ San Joaquin ___ ,
Brief Legal Description ____ A Portion of the N.W. 1/4 of Section 2, T.2 N., R.9 E. **CORNER TYPE** COORDINATES (Optional) Government Corner Control Elevation U.S. Survey Foot Meander Property Units Metric Rancho Other Horizontal Datum Zone Epoch Date May 28, 2024 Date of Survey Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8765(d) X 8771 8773 PLS Act Ref.: Other: Left as found Pre-Construction Established Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on July 1, 2024 P.L.S. or R.C.E. No. PLS 7889 Signed **COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received

October 9, 2024

and examined and filed

Signed

Title

County Surveyor's Comment



LEGEND:

R.S. RECORD OF SURVEY, BOOK AND PAGE, SAN

JOAQUIN COUNTY RECORDS

SEC. SECTION

FD. FOUND

FOUND MONUMENT AS NOTED

SET SPIKE WITH WASHER STAMPED "LS 7889"

DESCRIPTION:

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.

R.S. 25-25

SHELTON ROAD

FD. STEEL AXLE IN MOUND OF ROCKS AT 1/4 1/4 SEC. CORNER

ANGLE AND DISTANCE TABLE				
	BS-O-FS	ANGLE	BS DISTANCE	FS DISTANCE
	A-C-B	117°47'53"	50.00'	50.00'
			· · · · · · · · · · · · · · · · · · ·	