## CORNER RECORD

Agency Index Document Number San Joaquin Stockton County of City of California Lots 27, 28, M.&P. 19-33 Brief Legal Description CORNER TYPE COORDINATES (Optional) N. Government Corner Control Elevation X Property Meander U.S. Survey Foot Units Metric Other Rancho Horizontal Datum Zone \_\_\_\_\_ Epoch Date \_\_\_\_ Date of Survey September 5, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 X 8771 PLS Act Ref.: 8765(d) 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on September 5, 2024 PLS 7889 Signed P.L.S. or R.C.E. No. COUNTY SURVEYOR'S STATEMENT

nd filed October 24, 2024

P.L.S. OFR.C.E. No. 8657 This Corner Record was received and examined and filed Signed Title

**County Surveyor's Comment** 




## LEGEND:

M.&P. MAPS AND PLATS, BOOK AND PAGE, SAN JOAQUIN COUNTY RECORDS

- FOUND CHISELED CROSS
- FOUND 3/4" IRON PIPE TAGGED "R.C.E. 9924" IN MONUMENT WELL

## **DESCRIPTION:**

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.



|         | ANGLE AND DISTANCE TABLE |             |             |  |
|---------|--------------------------|-------------|-------------|--|
| BS-O-FS | ANGLE                    | BS DISTANCE | FS DISTANCE |  |
| A-C-B   | 163°27'07"               | 191.16'     | 165.44'     |  |