CORNER RECORD

Agency Index <u>CR - 24 - 397</u> Document Number City of STOCKTON County of SAN JOAQUIN Brief Legal Description FOUND 1/2" IRON PIPE, TAGGED LS 6406, IN DIRT, 279' ± NORTHWESTERLY OF QANTAS LANE, PER CR 10-045 **COORDINATES (Optional) CORNER TYPE** N. Elevation Government Corner | Control U.S. Survey Foot Meander Property Units Metric Other Rancho Horizontal Datum Zone Epoch Date _____ Date of Survey APRIL 24, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8773 Other: 8765(d) X 8771 PLS Act Ref .: Pre-Construction Left as found Established Rebuilt Corner/ Monument: Post-Construction Referenced Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 1/2" IRON PIPE, TAGGED LS 6406, IN DIRT, 279' ± NORTHWESTERLY OF QANTAS LANE, PER CR 10-045. SAN JOAQUIN COUNTY SURVEYOR'S RECORDS. THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with MAY 17, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received November 4, 2024. and examined and filed ames E. Hart P.L.Sor R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title

County Surveyor's Comment

