CORNER RECORD Agency Index Document Number City of County of SAN JOAQUIN Brief Legal Description FOUND 2-1/2" BRASS DISK AT THE INTERSECTION OF MARIPOSA RD AND SILVA ST. **CORNER TYPE** COORDINATES (Optional) N. Government Corner Control Elevation U.S. Survey Foot Meander Property Units Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey NOVEMBER 8, 2023 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8771 Other: PLS Act Ref .: 8765(d) Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 2-1/2" BRASS DISK COS MONUMENT STAMPED "5S-13" IN MONUMENT BOX AT THE INTERSECTION OF MARIPOSA RD AND SILVA ST AS SHOWN IN RECORD OF SURVEY BOOK 35, PAGE 5. THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with DECEMBER 1, 2023 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received and examined and filed LICENSE Signed SAN JOAQUIN COUNTY SURVEYOR

Page 1 of 2 BPELSG-2016

Title

County Surveyor's Comment

