Agency Index CORNER RECORD Document Number County of SAN JOAQUIN Brief Legal Description FOUND 1" IRON PIN, ALONG THE SOUTHEASTERLY RIGHT-OF-WAY LINE OF SILVA ST, AT MARIPOSA RD. COORDINATES (Optional) CORNER TYPE N. Government Corner Control Elevation V.S. Survey Foot Units Metric Property Meander Other Rancho Horizontal Datum Zone Epoch Date Date of Survey NOVEMBER 8, 2023 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 X 8771 8773 Other: 8765(d) PLS Act Ref .: Pre-Construction Established Rebuilt Left as found Corner/ Monument: Post-Construction X Referenced Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 1" IRON PIN, ALONG THE SOUTHEASTERLY RIGHT-OF-WAY LINE OF SILVA ST, AT MARIPOSA RD, AS SHOWN ON TRACT NO. 267, "SILVA GARDENS" VOL 13, PG 91. THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with DECEMBER 1, 2023 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT October 8, 2024 This Corner Record was received and examined and filed No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title County Surveyor's Comment

