## CORNER RECORD

CR-24-435 Agency Index Document Number .California County of SAN JOAQUIN Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099' IN DIRT ON THE EAST SIDE OF DEL MAR AVENUE, & 135'± NORTHERLY OF EAST MAIN STREET **COORDINATES (Optional) CORNER TYPE** E. N. Elevation Government Corner | Control U.S. Survey Foot Units Metric Meander Property Other Horizontal Datum Rancho Zone \_\_\_\_\_ Epoch Date Date of Survey MAY 15, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Left as found Established Corner/ Monument: Post-Construction Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, ON THE EAST SIDE OF DEL MAR AVENUE, & 135'± NORTHERLY OF EAST MAIN STREET, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on 9667 P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received November 22, 2024 and examined and filed **ICENSE** No. 8657 P.L.S or R.C.E. No. 8657 amos & Signed SAN JOAQUIN COUNTY SURVEYOR Title OF CALIF

Page 1 of 2

County Surveyor's Comment

