CORNER RECORD Agency Index Document Number .California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT ON THE EAST SIDE OF DEL MAR AVENUE, & 51'± NORTHERLY OF LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** N. E. Government Corner Control Elevation U.S. Survey Foot Metric **Property** Units Meander Other Rancho Horizontal Datum Zone Epoch Date Vertical Datum Date of Survey MAY 15, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Left as found Established Corner/ Monument: X Referenced Post-Construction Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, ON THE EAST SIDE OF DEL MAR AVENUE, & 51'± NORTHERLY OF LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on 9667 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT**

ovember 22, 2024

P.L.S. or R.C.E. No. 8657

Title SAN JOAQUIN COUNTY SURVEYOR

This Corner Record was received

and examined and filed

Signed

County Surveyor's Comment

Page 1 of 2

ICENSE

BPELSG-2016

