Agency Index CR-24-437 CORNER RECORD Document Number California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT NEAR THE NORTHEAST CORNER OF DEL MAR AVENUE & LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** E. ____ N. Government Corner Control Elevation U.S. Survey Foot Metric Property Units Meander Other Rancho Horizontal Datum Zone Epoch Date Date of Survey MAY 15, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Left as found Established Corner/ Monument: X Referenced Post-Construction Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, NEAR THE NORTHEAST CORNER OF DEL MAR AVENUE & LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 31,

Uc lober 31, 2029

and examined and filed

November 22, 2024.

Signed James & Hart

P.L.S or R.C.E. No. 8657

Title SAN JOAQUIN COUNTY SURVEYOR

County Surveyor's Comment

Page 1 of 2

LICENSE No. 8657

BPFI SG-2016

