
CORNER RECORD

CR-24-438 Agency Index Document Number .California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT NEAR THE SOUTHEAST CORNER OF DEL MAR AVENUE & LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** N. E. Government Corner Elevation Control U.S. Survey Foot Property Units Metric Meander Other Rancho Horizontal Datum Epoch Date Zone Date of Survey Vertical Datum MAY 15, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 PLS Act Ref.: 8765(d) Pre-Construction Rebuilt Established Left as found Corner/ Monument: Post-Construction Reestablished X Referenced Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, NEAR THE SOUTHEAST CORNER OF DEL MAR AVENUE & LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Aand Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT October 31, 2024 This Corner Record was received November 22, 2024 and examined and filed No. 8657 P.L.S. or R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title

Page 1 of 2

County Surveyor's Comment



BPELSG-2016 Page 2 of 2