CORNER RECORD

CR-24-439 Agency Index Document Number .California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT 99'± SOUTHWESTERLY FROM THE INTERSECTION OF DEL MAR AVENUE & LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** N. E.____ Elevation Government Corner | Control U.S. Survey Foot Property Units Metric Meander Other Rancho Horizontal Datum Zone Epoch Date Vertical Datum Date of Survey MAY 15, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 PLS Act Ref .: 8765(d) Pre-Construction Rebuilt Established Left as found Corner/ Monument: Reestablished X Referenced Post-Construction Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, 99'± SOUTHEASTERLY FROM INTERSECTION OF DEL MAR AVENUE & LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY **RECORDS** THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed **COUNTY SURVEYOR'S STATEMENT** October 31, 2024 This Corner Record was received November 22, 2024.

P.L.Sor R.C.E. No. 8657 and examined and filed LICENSE No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title

Page 1 of 2

County Surveyor's Comment

