Agency Index <u>CR - 24 - 440</u> CORNER RECORD Document Number California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 190'± NORTHERLY OF E MAIN STREET **COORDINATES (Optional) CORNER TYPE** N. E. ____ Government Corner Control Elevation ∇ U.S. Survey Foot Property Units Metric Meander Other Rancho Horizontal Datum Epoch Date Zone _____ Date of Survey MAY 15, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Left as found Established Corner/ Monument: Referenced Post-Construction Reestablished Found and tagged

FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 190'± NORTHERLY OF EAST MAIN STREET, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS

THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION.

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received

and examined and filed

November 22, 2024.

P.L.S. or R.C.E. No. 8657 Signed

SAN JOAQUIN COUNTY SURVEYOR Title

County Surveyor's Comment

See sheet #2 for description(s):

