## CORNER RECORD

CR-24-441 Agency Index Document Number California County of SAN JOAQUIN Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 308'± SOUTHERLY OF GASPARE WAY **COORDINATES (Optional) CORNER TYPE** N. E. Elevation Government Corner Control U.S. Survey Foot Property Units Metric Meander Other Horizontal Datum Rancho Epoch Date Zone Vertical Datum Date of Survey MAY 14, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8773 Other: 8771 PLS Act Ref.: 8765(d) Pre-Construction Rebuilt Established Left as found Corner/ Post-Construction Monument: Reestablished X Referenced Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 308'± SOUTHERLY OF GASPARE WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT October 31, 2024 This Corner Record was received November 22. LICENSE and examined and filed No. 8657 P.L.S or R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR OF CALIF Title **County Surveyor's Comment** 

Page 1 of 2

