## CORNER RECORD

CR-24-442 Agency Index Document Number ,California SAN JOAQUIN County of City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 362'± NORTHERLY OF LA SPEZIA WAY **COORDINATES (Optional)** CORNER TYPE N. Government Corner Control Elevation U.S. Survey Foot Property Units Metric Meander Other Rancho Horizontal Datum Epoch Date Zone Date of Survey MAY 14, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8771 8773 Other: 8765(d) PLS Act Ref .: Pre-Construction Established Rebuilt Left as found Corner/ Monument: Post-Construction Reestablished X Referenced Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 362'± NORTHERLY OF LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Aand Surveyors' Act on OCTOBER 25, 2024 P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received and examined and filed LICENSE P.L.S. or R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title

County Surveyor's Comment

