Agency Index CORNER RECORD Document Number California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 308"± NORTHERLY OF LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** N. E. Elevation Government Corner | Control U.S. Survey Foot Units Metric Meander Property Other Rancho Horizontal Datum Epoch Date Zone Date of Survey MAY 14, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 PLS Act Ref.: 8765(d) Pre-Construction Established Rebuilt Left as found Corner/ Monument: Referenced Reestablished Post-Construction Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 308'± NORTHERLY OF LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Aand Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed **COUNTY SURVEYOR'S STATEMENT** October 31, 2024 This Corner Record was received LICENSE and examined and filed No. 8657 P.L.S. or R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title

County Surveyor's Comment

