CORNER RECORD Agency Index Document Number County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 200'± NORTHERLY OF LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** Government Corner Control Elevation V.S. Survey Foot Metric Meander Property Units Other Rancho Horizontal Datum Zone Epoch Date Date of Survey MAY 14, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8773 X 8771 Other: PLS Act Ref.: 8765(d) Left as found Established Rebuilt Pre-Construction Corner/ Monument: Post-Construction Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 200'± NORTHERLY OF LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed

COUNTY SURVEYOR'S STATEMENT

ovember 22, 2024.

October 31, 2024

P.L.S. or R.C.E. No. 8657

County Surveyor's Comment

SAN JOAQUIN COUNTY SURVEYOR

This Corner Record was received

and examined and filed

Signed

Title

Dage 1 of 2

LICENSE

No. 8657

