Agency Index **CORNER RECORD** Document Number .California County of SAN JOAQUIN Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 147'± NORTHERLY OF LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** N. Government Corner Elevation Control V.S. Survey Foot Metric Units Property Meander Other Horizontal Datum Rancho Epoch Date _____ Zone Vertical Datum Date of Survey MAY 14, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 8771 8765(d) PLS Act Ref.: Pre-Construction Rebuilt Left as found Established Corner/ Post-Construction X Referenced Monument: Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 147'± NORTHERLY OF LA SPEZIA WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed LICENSE

County Surveyor's Comment

SAN JOAQUIN COUNTY SURVEYOR

No. 8657

OF CALL

Signed

Title

