Agency Index **CORNER RECORD** Document Number .California County of SAN JOAQUIN City of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 94'± NORTHERLY OF LA SPEZIA WAY **COORDINATES (Optional) CORNER TYPE** N. Elevation Government Corner | Control U.S. Survey Foot Metric **Property** Units Meander Other Horizontal Datum Rancho Zone Epoch Date Vertical Datum Date of Survey MAY 15, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Established Left as found Corner/ Post-Construction Monument: Reestablished X Referenced Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 94'± NORTHERLY OF LA SPEZIA WAY PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S, or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 22, 2024 and examined and filed LICENSE No. 8657 Hart P.L.S or R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title

County Surveyor's Comment

