CORNER RECORD Document Number _____ .California County of SAN JOAQUIN Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 204'± NORTHERLY OF GASPARE WAY **COORDINATES (Optional) CORNER TYPE** E. ____ Government Corner Elevation Control W.S. Survey Foot Metric Units Property Meander Other Horizontal Datum Rancho Zone Epoch Date Vertical Datum Date of Survey MAY 9, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref.: Pre-Construction Established Rebuilt Left as found Corner/ Post-Construction Reestablished X Referenced Monument: Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9009", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 204'± NORTHERLY OF GASPARE WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Aand Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT October 31, 2024 This Corner Record was received

November 22, 2024.

P.L.S. or R.C.E. No. 8657

County Surveyor's Comment

SAN JOAQUIN COUNTY SURVEYOR

and examined and filed

Signed

Title

LICENSE

No. 8657

