Agency Index CORNER RECORD Document Number County of SAN JOAQUIN Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE 147'± NORTHERLY OF GASPARE WAY COORDINATES (Optional) CORNER TYPE E. ____ N. Elevation Government Corner Control U.S. Survey Foot Metric Units Property Meander Other Horizontal Datum Rancho Zone Epoch Date Vertical Datum Date of Survey MAY 13, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref .: Pre-Construction Established Rebuilt Left as found Corner/ Post-Construction Referenced Monument: Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 147'± NORTHERLY OF GASPARE WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on 9667 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received LICENSE and examined and filed No. 8657 Signed

OF CALL

Page 1 of 2

SÁN JOAQUIN COUNTY SURVEYOR

County Surveyor's Comment

Title

