Agency Index _____CR-24-452 Document Number **CORNER RECORD** Document Number California County of SAN JOAQUIN Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 93'± SOUTHERLY OF GASPARE WAY **COORDINATES (Optional) CORNER TYPE** ____E. ____ N. Government Corner Control Elevation ∇ U.S. Survey Foot Metric Property Units Meander Other Horizontal Datum Rancho Zone Epoch Date Date of Survey MAY 14, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Left as found Established Corner/ Post-Construction Monument: X Referenced Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 93'± SOUTHERLY OF GASPARE WAY, PER (44 M&P 40), SAN JOAQUIN COUTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on 9667 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 22, 2024. PLS or R.C.E. No. 8657 and examined and filed LICENSE No. 8657 Signed

Page 1 of 2

County Surveyor's Comment

Title

SAN JOAQUIN COUNTY SURVEYOR

