Agency Index CORNER RECORD Document Number .California County of SAN JOAQUIN Brief Legal Description FOUNT 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 127'± SOUTHERLY OF GASPARE WAY **COORDINATES (Optional) CORNER TYPE** N. Government Corner Elevation Control U.S. Survey Foot Units Metric **Property** Meander Other Horizontal Datum Rancho Epoch Date Zone Vertical Datum Date of Survey MAY 14, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 X 8771 8765(d) PLS Act Ref.: Pre-Construction Rebuilt Left as found Established Corner/ Post-Construction Monument: X Referenced Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 127'± SOUTHERLY OF GASPARE WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on 9667 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received Dctober 31, 2024
and examined and filed November 22, 2024.
Signed P.L.Sor R.C.E. No. 8657
Title SAN JOAQUIN COUNTY SURVEYOR

County Surveyor's Comment

LICENSE No. 8657

OF CALIF

