CR-24-455 Agency Index **CORNER RECORD Document Number** .California SAN JOAQUIN County of Brief Legal Description FOUND 3/4" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, EAST OF DEL MAR AVENUE, 254'± SOUTHERLY OF GASPARE WAY **COORDINATES (Optional) CORNER TYPE** E. N. Elevation Government Corner Control ∇ U.S. Survey Foot Metric Property Units Meander Other Horizontal Datum Rancho Epoch Date Zone Vertical Datum Date of Survey MAY 14, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: X 8771 8765(d) PLS Act Ref.: Pre-Construction Rebuilt Established Left as found Corner/ Post-Construction Monument: Reestablished X Referenced Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG, "LS 9099", IN DIRT, EAST SIDE OF DEL MAR AVENUE, 254'± SOUTHERLY OF GASPARE WAY, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Aand Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed COUNTY SURVEYOR'S STATEMENT

| This Corner Record was received October 31, 2024 |
|--|
| and examined and filed November 22, 2024. |
| Signed James E Haut P.L.S or R.C.E. No. 8657 |
| Title SAN JOAQUIN COUNTY SURVEYOR |
| County Surveyor's Comment |



