## Agency Index CR-24-456 **CORNER RECORD** Document Number .California SAN JOAQUIN County of City of Brief Legal Description FOUND 1/2" IRON PIPE WITH PLASTIC PLUG "LS 9099" IN DIRT, NEAR THE SOUTHEAST CORNER OF DEL MAR AVENUE & HORNER AVENUE **COORDINATES (Optional) CORNER TYPE** N. Elevation Control Government Corner W.S. Survey Foot Metric Units Property Meander Other Horizontal Datum Rancho Epoch Date Zone Vertical Datum Date of Survey MAY 13, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8773 Other: 8771 8765(d) PLS Act Ref .: Pre-Construction Rebuilt Established X Left as found Corner/ Post-Construction X Referenced Monument: Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG, "LS 9099", IN DIRT NEAR THE SOUTHEAST CORNER OF DEL MAR AVENUE & HORNER AVENUE, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on 9667 P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT**

October 31, 2024

and examined and filed

November 22, 2024

Signed

P.L.S. or R.C.E. No. 8657

Title

SAN JOAQUIN COUNTY SURVEYOR

County Surveyor's Comment

This Corner Record was received

LICENSE

No. 8657

