## CORNER RECORD

CR-24-457 Agency Index Document Number ,California SAN JOAQUIN County of City of Brief Legal Description FOUND 1/2" IRON PIPE WITH THE PLASTIC PLUG "LS 9099" IN DIRT, EAST SIDE OF DEL MAR AVENUE, 76'± SOUTHERLY OF HORNER AVENUE **COORDINATES (Optional) CORNER TYPE** E. \_\_\_\_\_ N. Elevation Government Corner Control U.S. Survey Foot Metric Property Units Meander Rancho Other Horizontal Datum Epoch Date Zone Vertical Datum Date of Survey MAY 13, 2024 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 PLS Act Ref .: 8765(d) Pre-Construction Rebuilt Established Left as found Corner/ Post-Construction X Referenced Monument: Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, WITH PLASTIC PLUG "LS 9009", IN DIRT EAST SIDE OF DEL MAR AVENUE, 76'± SOUTHERLY OF HORNER AVENUE, PER (44 M&P 40), SAN JOAQUIN COUNTY RECORDS THIS MONUMENT HAS BEEN REFERENCED PRIOR TO CONSTRUCTION. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTS AND NO CLAIM IS MADE TO THEIR RELATIONSHIP TO THE BOUNDARY LOCATION SHOWN HEREON. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with OCTOBER 25, 2024 the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9667 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received LICENSE and examined and filed No. 8657 P.L.S. or R.C.E. No. 8657 Signed SAN JOAQUIN COUNTY SURVEYOR Title **County Surveyor's Comment** 

Page 1 of 2

